

Service Bulletin

DATE December 17, 1975

NUMBER 2933 20001

ATTENTION: SERVICE MANAGERS AND OWNERS	GROUP
1. <u>DESCRIPTION</u>	33
<p>This bulletin provides instructions for replacement of non-specification shower curtains installed on motor homes between serial numbers 00001 to 00952 approximately.</p>	SUBJECT SHOWER CURTAIN 5108376 Polycube Curtain Color: White Only
<p>2. <u>DEALER</u></p> <p>Dealers must comply with this bulletin prior to delivery of new coach (if within indicated serial range) to an owner. Please order new shower curtain by part number 5108376 and supply coach serial number with your purchase order. If so requested by an owner, dealers may ship this shower curtain direct to an owner (see next paragraph).</p>	MODEL (S) AFFECTED MOTOR HOMES 00001 TO 00952 Approximately
<p>3. <u>OWNERS</u></p> <p>Owners may return coach to dealer for this modification, or if you desire ask your dealer to ship the new shower curtain to you. If you, the owner, do your own installation it is up to you to make a proper installation and neither the dealer nor FMC/MCD will assume responsibility for damage due to improper installation or failure to install this new curtain (#5108376).</p> <p>If you want your dealer to make the installation contact him and make an appointment for curtain installation as soon as practicable after receipt of this bulletin.</p>	(Factory Use Only) Information added to: OWNER MANUAL (S) SERVICE MANUAL (S) PARTS MANUAL (S)
<p>4. <u>MANPOWER</u></p> <p>Estimated accomplishment time for one mechanic is approximately 1/4 hour.</p>	WARRANTY MANUAL (S)
<p>5. <u>WARRANTY REIMBURSEMENT</u></p> <p>FMC Motor Coach Division will allow a maximum of 1/4 labor hour and reimbursement for one shower curtain #5108376 per coach on a properly filled submitted warranty claim (form MCD 69) for this modification.</p>	OTHER RECEIVED JAN 5 1976

Service Bulletin

DATE December 17, 1975

NUMBER 2933 20001

ATTENTION: SERVICE MANAGER S AND OWNERS	GROUP 33
<p>6. <u>ACCOMPLISHMENT INSTRUCTIONS</u></p> <p>Remove old shower curtain from rod and replace with new curtain #5108376.</p> <p>NOTE: After installation caution owners that shower curtain must be cleaned in accordance with instructions sewed into the label at top of each curtain.</p>	<p>SUBJECT SHOWER CURTAIN 5108376 Polycube Curtain Color: White Only</p> <p>MODEL (S) AFFECTED MOTOR HOMES 00001 TO 00952 Approximately</p>
<p style="text-align: center;"><i>Wayne J. Biondi</i></p> <p style="text-align: center;">WAYNE J. BIONDI SERVICE MANAGER</p>	<p>(Factory Use Only) Information added to:</p> <p>OWNER MANUAL (S)</p>
	<p>SERVICE MANUAL (S)</p>
	<p>PARTS MANUAL (S)</p>
	<p>WARRANTY MANUAL (S)</p>
<p>OTHER</p> <p style="text-align: right; color: red; font-weight: bold;">RECEIVED JAN 5 1976</p>	