



**FMC CORPORATION**

**RECREATIONAL VEHICLES DIVISION**

883 BROKAW ROAD, BOX 664, SANTA CLARA, CALIFORNIA 95052 • TELEPHONE: (408) 289-0111

30 March 1973

TO: All Service Managers and Coach Owners

Attached is Service Bulletin 2941-30001 advising of precaution to be taken when the winterizing kit for the off-road (domestic) cooling system is installed.

Please make certain all model 2900R coaches, now in your possession or in hands of an owner, are in compliance with the instructions contained in the bulletin.

Yours truly,

*John L. Strever*  
JOHN L. STREVER  
Service Manager

JLS/jh  
Enclosure

**F.M.C., AS OF 12/31/75, NO LONGER  
HONORS PARTS OR LABOR REIMBURSEMENT  
AS OUTLINED IN THIS BULLETIN**



# Service Bulletin

DATE March 30, 1973

NUMBER 2941 30001

<p><b>ATTENTION: SERVICE MANAGERS and Owners</b></p>	<p>GROUP 41</p>
<p>This Service Bulletin serves to advise you of a method for de-winterizing the off-road (domestic) cooling system.</p> <p>As part of the air conditioner winterizing kit provided with each coach, the "Service Access" for the off-road cooling (fig. 5-21, page 5-15 of Owners Manual) is sealed with two foam pads. In addition, the exhaust vent for the off-road cooling, located on the under-side of the coach below the air conditioning units, is sealed with a winterizing pan attached with four sheet metal screws.</p> <p>To avoid overheating and possible damage to the air conditioning units, the two foam pads and winterizing pan must be removed and stored during seasons when these air conditioning units will be in use.</p> <p>To eliminate any chance the air conditioners will be turned ON during the cold months when the winterizing parts are installed, it is a good practice to open the two 20 amp circuit breakers that control these units (fig. 5-32, page 5-29 of the Owners Manual). The two circuit breakers are the right hand breakers (viewed when looking at the box) on lines 2 and 3 inside the box.</p>	<p>SUBJECT          OFF-ROAD          (DOMESTIC) AIR          CONDITIONING          SYSTEM</p>
	<p>MODEL (S)          AFFECTED</p> <p>2900R</p>
	<p>(Factory Use Only)          Information          added to:</p>
	<p>OWNER MANUAL (S)</p>
	<p>SERVICE MANUAL (S)</p>
<p>PARTS MANUAL (S)</p>	
<p>WARRANTY MANUAL (S)</p>	
<p>OTHER</p>	
<p><i>John L. Strever</i>          John Strever          Service Manager</p>	