

Group 31 Interior Doors and Cabinetry

GENERAL: This group contains information on all interior storage cabinets in the kitchen, rear bedroom, and dinette areas.

SPECIFICS: As applicable

...Bath and Shower Vanity Cabinets and Sink

...Clothes Closets

...Closet and Vanity Mirrors

...Dinette Cabinets

...Folding Doors

...Food Storage Cabinets

...Kitchen Cabinets and Sink

...Range/Oven Cabinets

...Refrigerator Cabinets





URGENT

ROUTINE


MANDATORY

INFORMATIONAL

Service Bulletin

DATE 5 April 1974

NUMBER 2931 40001

| | |
|--|---|
| ATTENTION: SERVICE MANAGERS AND OWNERS | GROUP 31 |
| <p><u>DESCRIPTION</u></p> <p>The furnace thermostat mounted on the bathroom wall, adjacent to the refrigerator, is often struck by the freezer door, refrigerator door, or both doors when they are opened. To protect the thermostat from damage, a door bumper (RVD 5101810) has been added to the wall just to the right of the thermostat.</p> <p><u>INSTALLATION</u></p> <p>Locate bumper so that it protects the thermostat when either or both of the refrigerator doors are opened. Bumper screws into wood panel adjacent to the thermostat.</p> <p><u>OWNERS</u></p> <p>If your coach is not equipped with such a bumper, make a request for it through your dealer. Allow ample time for delivery since the parts will be supplied to dealers only upon request by you.</p> <p><u>DEALERS</u></p> <p>Orders for the above part should be placed with FMC/RVD Service Department via the standard parts ordering procedure now in effect. They will be supplied to you at no cost.</p> <p style="text-align: center;"> JOHN L. STREVER Service Manager</p> | <p>SUBJECT</p> <p>REFRIGERATOR DOOR STOP THERMOSTAT PROTECTION</p> <hr/> <p>MODEL (S) AFFECTED</p> <p>2900R</p> <hr/> <p>(Factory Use Only) Information added to:</p> <p>OWNER MANUAL (S)</p> <hr/> <p>SERVICE MANUAL (S)</p> <hr/> <p>PARTS MANUAL (S)</p> <hr/> <p>WARRANTY MANUAL (S)</p> <hr/> <p>OTHER</p> |