

Group 33 Carpeting and Drapes

GENERAL: This group contains information on all interior carpets, drapes, and window shades.

SPECIFICS: As applicable

...Bath Valance and Hardware

...Carpeting and Trim

...Drapes and Tracks

...Shower Curtain and Hardware

...Window Shades and Hardware



FMC Corporation  
Recreational Vehicle Division  
333 Brokaw Road Box 664 Santa Clara, California 95052

FMC Corporation  
Motor Coach Division  
333 Brokaw Road Box 664  
Santa Clara California 95052  
(408) 2890111

33

**FMC**

12/17/75

Dear FMC Motor Coach Owner:

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

The Motor Coach Division of FMC Corporation has determined that a defect which relates to the vehicles safety exists in your motor coach. In particular the shower curtain.

We are sending this notification to urge you to contact the nearest FMC Dealer to have this retro-fit taken care of as soon as possible.

Although you may think that the shower curtain installed in your motor coach is adequate, we at FMC as well as United States Department of Transportation deem it important because the curtain doesn't meet the flammability of interior materials.

If you would promptly contact your closest FMC Dealer (See enclosed List) and make an appointment, the Dealer can then call for the new curtain and have them available upon your appointment date. If there isn't an FMC Dealer within a reasonable distance, contact Motor Coach Division, Bud Richards, Motor Homes Service Supervisor ( Area Code 408 289-3665.)

If you no longer own the vehicle, would you please supply FMC Service with the new owners name and address for follow-up.

I am sorry to cause you this inconvenience, however, we have taken this action in the interest of your safety.

Sincerely,

*Wayne J. Biondi*  
WAYNE J. BIONDI  
Service Manager

WJB/pf

Enclosure

Dealer List



# Service Bulletin

DATE December 17, 1975

NUMBER 2933 20001

ATTENTION: SERVICE MANAGER S AND OWNERS		GROUP
1. <u>DESCRIPTION</u>		33
<p>This bulletin provides instructions for replacement of non-specification shower-curtains installed on motor homes between serial numbers 00001 to 00952 approximately.</p>		SUBJECT
2. <u>DEALER</u>		SHOWER CURTAIN 5108376 Polycube Curtain Color: White Only
<p>Dealers must comply with this bulletin prior to delivery of new coach (if within indicated serial range) to an owner. Please order new shower curtain by part number 5108376 and supply coach serial number with your purchase order. If so requested by an owner, dealers may ship this shower curtain direct to an owner (see next paragraph).</p>		MODEL(S) AFFECTED
3. <u>OWNERS</u>		MOTOR HOMES 00001 TO 00952 Approximately
<p>Owners may return coach to dealer for this modification, or if you desire ask your dealer to ship the new shower curtain to you. If you, the owner, do your own installation it is up to you to make a proper installation and neither the dealer nor FMC/MCD will assume responsibility for damage due to improper installation or failure to install this new curtain (#5108376) -</p> <p>If you want your dealer to make the installation contact him and make an appointment for curtain installation as soon as practicable after receipt of this bulletin.</p>		(Factory Use Only) Information added to:
4. <u>MANPOWER</u>		OWNER MANUAL(S)
<p>Estimated accomplishment time for one mechanic is approximately 1/4 hour.</p>		SERVICE MANUAL(S)
5. <u>WARRANTY REIMBURSEMENT</u>		PARTS MANUAL(S)
<p>FMC Motor Coach Division will allow a maximum of 1/4 labor hour and reimbursement for one shower curtain #5108376 per coach on a properly filled submitted warranty claim (form MCD 69) for this modification.</p>		WARRANTY MANUAL(S)
		OTHER



FMC Corporation  
 Motor Coach Division  
 323 Brookway Road Box 664 Santa Clara California 95052

URGENT       ROUTINE  
 MANDATORY       INFORMATIONAL

# Service Bulletin

DATE December 17, 1975

NUMBER 2933 20001

ATTENTION: SERVICE MANAGERS AND OWNERS	GROUP
6. <u>ACCOMPLISHMENT INSTRUCTIONS</u>	33
<p>Remove old shower curtain from rod and replace with new curtain #5108376.</p> <p>NOTE: After installation caution owners that shower curtain must be cleaned in accordance with instructions sewed into the label at top of each curtain.</p>	<p>SUBJECT</p> <p>SHOWER CURTAIN  5108376 Polycube  Curtain  Color: White  Only</p>
	<p>MODEL (S)  AFFECTED</p> <p>MOTOR HOMES  00001 TO 00952  Approximately</p>
<p style="text-align: center;"><i>Wayne J. Biondi</i></p> <p style="text-align: center;">- WAYNE J. BIONDI  SERVICE MANAGER</p>	<p>(Factory Use Only)  Information added to:</p> <p>OWNER MANUAL (S)</p>
	<p>SERVICE MANUAL (S)</p> <p>PARTS MANUAL (S)</p>
	<p>WARRANTY MANUAL (S)</p> <p>OTHER</p>